timeTec
www.timeteccloud.com

D3180S

Metal Detectors with a Fever Detection

Installation Guide

① Control Unit Case
② Alarm zone LED
③ Built-in Probe
④ Infrared Sensors
⑤ Waterproof Foot Cover
⑥ Power Line Interface

Left door panel

Right door panel

1. Remove the package of control unit and door panel.

2. Put the control unit case and door panels as above picture shown, then connect the left and right door panel with the control unit case by bolts and nuts. Tighening screws.

3. Probe line of the left and right door panel tight inserted into the motherboard corresponding socket respectively.

4. Install the screw on the control unit case cover.

5. Lift the walk through metal detector to the vertical position and move to the assigned position.

TECHNICAL PARAMENTE

Input voltage: 100-240V, 50/60Hz

Power supply: AC100V~240V

Gross weight: 65KG

Working temperature: -20℃~50℃

Alarm: Visible and audible alarm

Inner Dimensions (mm): 2000 (H) x 700 (W) x 605 (D)

External Dimensions (mm): 2230 (H) x 830 (W) x 730 (D)